
FIG.1



K-1962

FIG.2






FIG.3



## (FIRST DRUM SIDE PERFORATING OPERATION)



## (SECOND DRUM SIDE PERFORATING OPERATION)




FIG.6A








FIG.6B











STENCIL SHEET TRANSFER AMOUNT



K-1962 10/11

FIG.10



K-1962